Material Science and Metallurgy

Topic:~Iron Iron-Carbide Diagram (Basic Definitions & States)

Mechanical Department

- •Various phases that appear on the Iron-Carbon equilibrium phase diagram are as under:
 - Austenite
 - •Ferrite
 - Pearlite
 - •Cementite
 - Martensite
 - •Ledeburite

- Ferrite is known as α solid solution.
- It is an interstitial solid solution of a small amount of carbon dissolved in α (BCC) iron.
- stable form of iron below 912 deg.C
- The maximum solubility is 0.025 % C at 723 deg.C and it dissolves only 0.008 % C at room temperature.
- It is the softest structure that appears on the diagram.

• Ferrite

- Average properties are:
 - Tensile strength = 40,000 psi;
 - Elongation = 40 %



- Pearlite is the eutectoid mixture containing 0.80 % C and is formed at 723 deg.C on very slow cooling.
- It is a very fine plate like or lamellar mixture of ferrite and cementite.
- The white ferrite background or matrix contains thin plates of cementite (dark).



- Austenite is an interstitial solid solution of Carbon dissolved in γ (F.C.C.) iron.
- Maximum solubility is 2.0 % C at 1130 deg.C.
- High formability, most of heat treatments begin with this single phase.
- It is normally not stable at room temperature. But, under certain conditions it is possible to obtain austenite at room temperature.

Austenite

- Average properties are:
 - Tensile strength=150,000 psi;
 - Elongation = 10%



- Cementite or iron carbide, is very hard, brittle intermetallic compound of iron & carbon, as Fe₃C, contains 6.67 % C.
- It is the hardest structure that appears on the diagram, exact melting point unknown.
- It is has
 - low tensile strength (approx. 5,000 psi), but
 - high compressive strength.

- Ledeburite is the eutectic mixture of austenite and cementite.
- It contains 4.3 percent C and is formed at 1130°C.

- Martensite a super-saturated solid solution of carbon in ferrite.
- It is formed when steel is cooled so rapidly that the change from austenite to pearlite is suppressed.

Iron Iron-Carbide Diagram

The Iron-Iron Carbide Diagram

- A map of the temperature at which different phase changes occur on very slow heating and cooling in relation to Carbon, is called Iron- Carbon Diagram.
- Iron- Carbon diagram shows
 - The type of alloys formed under very slow cooling,
 - Proper heat-treatment temperature and
 - How the properties of steels and cast irons can be radically changed by heat-treatment.

How to read the Fe-C phase diagram



Various Features of Fe-C diagram



FIGURE 9.22 The iron-iron carbide phase diagram. (Adapted from *Binary* Alloy Phase Diagrams, 2nd edition, Vol. 1, T. B. Massalski, Editor-in-Chief, 1990. Reprinted by permission of ASM International, Materials Park, OH.)

Reactions

Peritectic L + $\delta = \gamma$

Eutectic $L = \gamma + Fe_3C$

Eutectoid
$$\gamma = \alpha + Fe_3C$$

Phases present



δ BCC structure Paramagnetic α ferriteBCC structureFerromagneticFairly ductile

γ austenite FCC structure Non-magnetic ductile Fe₃C cementite Orthorhombic Hard brittle

Max. solubility of C in ferrite=0.022%

Max. solubility of C in austenite=2.11%

Three Phase Reactions

- Peritectic, at 1490 deg.C, with low wt% C alloys (almost no engineering importance).
- Eutectic, at 1130 deg.C, with 4.3wt% C, alloys called cast irons.
- Eutectoid, at 723 deg.C with eutectoid composition of 0.8wt% C, two-phase mixture (ferrite & cementite). They are steels.

The Iron-Iron Carbide Diagram

- The diagram shows three horizontal lines which indicate isothermal reactions (on cooling / heating):
- First horizontal line is at 1490°C, where peritectic reaction takes place:

Liquid + $\delta \leftrightarrow$ austenite

Second horizontal line is at 1130°C, where eutectic reaction takes place:

liquid \leftrightarrow austenite + cementite

 Third horizontal line is at 723°C, where eutectoid reaction takes place:

Delta region of Fe-Fe carbide diagram



Ferrite region of Fe-Fe Carbide diagram



Showing the Extent to Which Carbon is Soluble in a Iron.



In order to understand the transformation processes, consider a steel of the eutectoid composition. 0.8% carbon, being slow cooled along line x-x'.

 At the upper temperatures, only austenite is present, with the 0.8% carbon being dissolved in solid solution within the FCC. When the steel cools through 723°C, several changes occur simultaneously.

- The iron wants to change crystal structure from the FCC austenite to the BCC ferrite, but the ferrite can only contain 0.02% carbon in solid solution.
- The excess carbon is rejected and forms the carbon-rich intermetallic known as cementite.

- Hypo-eutectoid steels: Steels having less than 0.8% carbon are called hypo-eutectoid steels (hypo means "less than").
- Consider the cooling of a typical hypo-eutectoid alloy along line y-y'.
- At high temperatures the material is entirely austenite.
- Upon cooling it enters a region where the stable phases are ferrite and austenite.
- The low-carbon ferrite nucleates and grows, leaving the remaining austenite richer in carbon.

- Hypo-eutectoid steels- At 723°C, the remaining austenite will have assumed the eutectoid composition (0.8% carbon), and further cooling transforms it to pearlite.
- The resulting structure, is a mixture of *primary* or *proeutectoid ferrite* (ferrite that forms before the eutectoid reaction) and regions of pearlite.



- Hyper-eutectoid steels (hyper means "greater than") are those that contain more than the eutectoid amount of Carbon.
- When such a steel cools, as along line *z-z'*, the process is similar to the hypo-eutectoid steel, except that the primary or pro-eutectoid phase is now cementite instead of ferrite.

- As the carbon-rich phase nucleates and grows, the remaining austenite decreases in carbon content, again reaching the eutectoid composition at 723°C.
- This austenite transforms to pearlite upon slow cooling through the eutectoid temperature.
- The resulting structure consists of primary cementite and pearlite.
- The continuous network of primary cementite will cause the material to be extremely brittle.



Hypo-eutectoid steel showing primary cementite along grain boundaries pearlite

- When the alloys are cooled rapidly, entirely different results are obtained, since sufficient time may not be provided for the normal phase reactions to occur.
- In these cases, the equilibrium phase diagram is no longer a valid tool for engineering analysis.
- Rapid-cool processes are important in the heat treatment of steels and other metals (to be discussed later in H/T of steels).

Principal phases of steel and their Characteristics

Phase	Crystal structure	Characteristics
Ferrite	BCC	Soft, ductile, magnetic
Austenite	FCC	Soft, moderate strength, non- magnetic
Cementite	Compound of Iron & Carbon Fe ₃ C	Hard &brittle

Thank You.!